


... mechanical design using the different coordinate entry menu



the Erase command and use all the different coordinate entry methods

